

Field Notice Of Noncompliance For Tribally Owned/Managed Facility



No.084

The Federal Environmental Protection Agency (EPA) is responsible for administration of underground storage tank (UST) laws on Indian Lands. Pursuant to federal regulation at 40 CFR Part 280, during an inspection on 6-/4-20/4 at this facility owned or operated by the Tribal Government, the following items of UST noncompliance were observed:

1	
Failure to Maintain tank release detection records.	Repair CSLD function of Tank monitor. Print and save leak test reports each month.
Description:	Corrections Nelded: Or not out liquid State Report each month,
3) Description: Fix and Packet above	Provide next two months of
on Vegolex-Root Tenk monitor problède documentation	(July-August) Bx August 31, 2016

This is **not** a notice of formal enforcement action. Consistent with the federal government trust relationship with tribes, EPA is providing this notice of its concern about the above-described noncompliance and its interest in working cooperatively with the tribal government to implement changes necessary for compliance. EPA is willing to provide technical assistance, as our resources allow, and would like the Tribe to respond by making a commitment to return to compliance in a timely manner. If compliance is achieved, EPA would not expect to take a formal enforcement action.

Tribal Official To Serve As Primary Con	tact Regarding This Notice	EPA Technical Assistance Contact
Name: Lesle Rima	Tribe:	Name: JIM G(eeves
Signature (and date, if after inspection):	Phone: 509-244-0164	Office Address: 300 Desmond Dr SE 102
Name of Fagility: SOOKO West Plains	Facility ID#:	Locel WA 98503
Address: 14212 W, Hw/2		Phone: 360-951-6046
Medical Loke WA 9	79022	Signature: Uhooves

The violation(s) noted above have been described to me in satisfactory detail by the EPA-technical assistance contact.

Signature of On-Site Facility Manager (if different from above)